| REPORT OF ANNUAL INSPECTION OF CCR LANDFILL | |
|---|--------|
| CCR LANDFILL NAME: Plant Daniel Gypsum Storage Facility | |
| OWNER OF CCR LANDFILL: Mississippi Power Company | |
| INSPECTION DATE: October 13, 2022 | |
| INSPECTING ENGINEER: Jacob A. Jordan, PE MS PE 27315 | |
| APPROXIMATE VOLUME OF CCR CONTAINED IN THE UNIT AT | 60,000 |
| THE TIME OF INSPECTION (CU. YDS.) | |
| ANY CHANGES IN GEOMETRY OF THE CCR UNIT SINCE THE | |
| PREVIOUS ANNUAL INSPECTION? | NO |
| (IF YES, DESCRIBE): | |
| | |
| | |
| | |
| | |
| | |
| ANY APPEARANCE OF AN ACTUAL OR POTENTIAL STRUCTURAL | |
| WEAKNESS OF THE CCR UNIT, OR ANY EXISTING CONDITIONS | |
| THAT ARE DISRUPTING OR HAVE THE POTENTIAL TO DISRUPT | NO |
| THE OPERATION AND SAFETY OF THE CCR UNIT OR | |
| APPURTENANT STRUCTURES? | |
| (IF YES, DESCRIBE): | |
| | |
| | |
| | |
| | |
| | |
| ANY OTHER CHANGE(S) WHICH MAY HAVE AFFECTED THE | |
| STABILITY OR OPERATION SINCE THE PREVIOUS ANNUAL | NO |
| INSPECTION? | |
| (IF YES, DESCRIBE): | |
| | |
| | |
| | |
| | |
| | |
| WERE ALL CORRECTIVE ACTIONS IDENTIFIED DURING THE | N1/A |
| PREVIOUS ANNUAL INSPECTION COMPLETED? | N/A |
| (IF NO, DESCRIBE): | |
| | |
| | |
| | |
| | |
| | |